



80960KA/KB

SPECIFICATION UPDATE

Release Date: July, 1996

Order Number: 272851-001

The 80960KA/KB may contain design defects or errors known as errata. Characterized errata that may cause the 80960KA/KB's behavior to deviate from published specifications are documented in this specification update.



Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

The 80960KA/KB may contain design defects or errors known as errata. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

* Third-party brands and names are the property of their respective owners.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation
P.O. Box 7641
Mt. Prospect, IL 60056-7641

or call in North America 1-800-879-4683, Europe 44-0-1793-431-155, France 44-0-1793-421-777,

Germany 44-0-1793-421-333 other Countries 708-296-9333

Copyright © 1996, Intel Corporation

CONTENTS

REVISION HISTORY	1
PREFACE	2
SUMMARY TABLE OF CHANGES	4
IDENTIFICATION INFORMATION	6
ERRATA	8
SPECIFICATION CHANGES	9
SPECIFICATION CLARIFICATIONS	9
DOCUMENTATION CHANGES	9

REVISION HISTORY

Intel has manufactured the 80960KA/KB under two series of steppings, known respectively as "Non-Shrink" and "Shrink" to denote manufacturing processes. Intel currently manufactures all 80960KA/KB devices using the "Shrink" Process 648. Therefore, the complete name of the C stepping is "Shrink C" stepping.

The C stepping corrected a number of errata and incorporated other changes to improve manufacturability in plastic packages. Minor changes have since been made via segmentation and metal line organization for manufacturability. There have been no further logic modifications.

Date of Revision	Version	Description
07/01/96	001	This is the new Specification Update document. It contains all identified errata published prior to this date.



PREFACE

As of July, 1996, Intel's Semiconductor Products Group has consolidated available historical device and documentation errata into this new document type called the Specification Update. We have endeavored to include all documented errata in the consolidation process, however, we make no representations or warranties concerning the completeness of the Specification Update.

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This is the first release of the 80960KA/KB Specification Update. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain additional information that was not previously published.

Affected Documents/Related Documents

Electrical specifications for these products are found in the following documents:

Title	Order
<i>80960KA Embedded 32-Bit Processor</i> datasheet	270775-005
<i>80960KB Embedded 32-Bit Processor with Integrated Floating-Point Unit</i> datasheet	270565-007

Functional descriptions for these products are found in the following documents:

Title	Order
<i>i960® KA/KB Microprocessor Programmer's Reference Manual</i>	270567-003
<i>80960KB Hardware Designer's Reference Manual</i>	270564-002

Nomenclature

Errata are design defects or errors. These may cause the published (component, board, system) behavior to deviate from published specifications. Hardware and software designed to be used with any component, board, and system must consider all errata documented.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in any new release of the specification.

NOTE:

Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

SUMMARY TABLE OF CHANGES

The following table indicates the errata, specification changes, specification clarifications, and documentation changes which apply to the 80960KA/KB product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Steps

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page):	Page location of item in this document.
---------	---

Status

Doc:	Document change or update will be implemented.
Fix:	This erratum is intended to be fixed in a future step of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Eval:	Plans to fix this erratum are under evaluation.

Row

	Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.
--	---

Errata

No.	Steppings			Page	Status	ERRATA
	A	B	C			
9600001			X	8	NoFix	ALE# Does Not Function in Secondary Bus Master Mode
9600002			X	8	NoFix	Problem Using HLDA and ADS# with Asynchronous Logic
9600003			X	9	NoFix	Breakpoint Register Initialization

Specification Changes

No.	Steppings			Page	Status	SPECIFICATION CHANGES
	#	#	#			
						None for this revision of this specification update.

Specification Clarifications

No.	Steppings			Page	Status	SPECIFICATION CLARIFICATIONS
	#	#	#			
						None for this revision of this specification update.

Documentation Changes

No.	Document Revision	Page	Status	DOCUMENTATION CHANGES
				None for this revision of this specification update.

IDENTIFICATION INFORMATION

Markings

As of January 1994, all 80960KA/KB, A80960KA/KB, TA80960KA/KB, and NG80960KA devices will be marked with stepping numbers.

Unless otherwise documented, 80960KA/KB devices marked with other specification numbers belong to different steppings. Be sure you have a correct technical bulletin for the devices at hand.

Stepping register

The following table applies to all C stepping devices:

Part Number	Specification Number	Package	Status
A80960KA	C	PGA-132	Current
A80960KB	C	PGA-132	Current
TA80960KA	C	PGA-132 Extended Temp.	Current
TA80960KB	C	PGA-132 Extended Temp.	Current
NG80960KA	C	PQFP-132	Current
NG80960KB	C	PQFP-132	Current
TG80960KA	C	PQFP-132 Extended Temp	Current
TG80960KB	C	PQFP-132 Extended Temp	Current
A80960KA-10	S V835	PGA-132	Obsolete
TA80960KA-10	S V862	PGA-132 Extended Temp.	Obsolete
A80960KA-16	S V806	PGA-132	Obsolete
TA80960KA-16	S V863	PGA-132 Extended Temp.	Obsolete
A80960KA-20	S V807	PGA-132	Obsolete
TA80960KA-20	S V864	PGA-132 Extended Temp.	Obsolete
A80960KA-25	Q 348	PGA-132 Special	Obsolete
A80960KA-25	S I25	PGA-132 Special	Obsolete
A80960KA-25	S N098	PGA-132 Special	Obsolete
A80960KA-25	S V808	PGA-132	Obsolete
TA80960KA-25	Q 348	PGA-132 Special	Obsolete

TA80960KA-25	S V865	PGA-132 Extended Temp.	Obsolete
QA80960KA-25	Q 348	PGA-132 Extended BI	Obsolete
A80960KB-10	S V836	PGA-132	Obsolete
TA80960KB-10	S V866	PGA-132 Extended Temp.	Obsolete
A80960KB-16	S V809	PGA-132	Obsolete
TA80960KB-16	S V867	PGA-132 Extended Temp.	Obsolete
A80960KB-20	S I25	PGA-132 Special	Obsolete
A80960KB-20	S V810	PGA-132	Obsolete
LA80960KB-20	S W137	PGA-132 Ext. Temp & BI	Obsolete
TA80960KB-20	S V868	PGA-132 Extended Temp.	Obsolete
A80960KB-25	Q 8276	PGA-132	Obsolete
A80960KB-25	S V811	PGA-132	Obsolete
TA80960KB-25	S V869	PGA-132 Extended Temp.	Obsolete
A80960MC-16	S V942	PGA-132 Special	Obsolete
KD80960KA-10	S V777	PQFP-132 Multi-Layer	Obsolete
KD80960KA-10	S V972	PQFP-132 Multi-Layer	Obsolete
KD80960KA-16	S V483	PQFP-132 Multi-Layer	Obsolete
KD80960KA-20	S V484	PQFP-132 Multi-Layer	Obsolete
KD80960KB-10	S V778	PQFP-132 Multi-Layer	Obsolete
KD80960KB-16	S V485	PQFP-132 Multi-Layer	Obsolete
KD80960KB-20	S V486	PQFP-132 Multi-Layer	Obsolete
NG80960KA-10	S V925	PQFP-132	Obsolete
NG80960KA-16	S V926	PQFP-132	Obsolete
NG80960KA-20	S V927	PQFP-132	Obsolete
NG80960KA-20	S W158	PQFP-132 Special	Obsolete
NG80960KA-25	Q 8117	PQFP-132 Special	Obsolete
NG80960KB-10	S V928	PQFP-132	Obsolete
NG80960KB-16	S V929	PQFP-132	Obsolete
NG80960KB-20	S V930	PQFP-132	Obsolete

ERRATA

9600001. *ALE# Does Not Function in Secondary Bus Master Mode*

PROBLEM: When two 80960KA/KB processors share the same local bus in a Primary Bus Master (PBM)/Secondary Bus Master (SBM) relationship, ALE# does not work on the Secondary Bus Master.

IMPLICATION: This erratum effectively makes "bus re-enter" operation impossible.

WORKAROUND: None.

STATUS: Refer to Summary Table of Changes to determine the affected stepping(s).

9600002. *Problem Using HLDA and ADS# with Asynchronous Logic*

PROBLEM: Asynchronous logic connected to the HLDA and ADS# pins may malfunction due to ground bounce on these outputs. The problem occurs when address/data buffers switch from a high state to a low state.

This problem exists on devices in both the PGA and PQFP packages. On the 80960KA/KB device, the LAD bus buffers share a ground with the buffers for the ADS#, HLDA, DT/R#, W/R#, ALE#, BE2#, BE1#, BE0#, CACHE and INTA pins. In addition to ground bounce on the ADS# and HLDA pins, it may be possible to observe ground bounce, undershoot and overshoot on other pins from this group.

The problem depends on how many outputs switch, proximity to the switching outputs and proximity to ground pads on the die. The worst case situation occurs when all address/data outputs switch simultaneously.

IMPLICATION: None

WORKAROUND: Logic external to the 80960KA/KB processor should sample HLDA synchronously on an "A" or "D" clock edge. ADS# can be sampled synchronously on an "A", "C", or "D" clock edge. Check setup and hold times carefully.

All 80960KA/KB processor designs must consider good power and ground distribution and decoupling techniques. As with all i960 family designs, a multi-layer circuit board is recommended. Use of a multi-layer board will not eliminate this problem, but may lessen its effects.

STATUS: Refer to Summary Table of Changes to determine the affected stepping(s).

960003. Breakpoint Register Initialization

PROBLEM: There are two breakpoint registers on the 80960Kx. These registers can be written using the Set Breakpoint Register IAC only, and they cannot be read. Bits 2-31 of the register contain the address on which to break, and bit 1 enables or disables the breakpoint. These registers are not set to a specific value during initialization, and may be enabled upon powerup. This could cause sporadic breakpoints to occur if tracing is enabled in the process controls and breakpoint trace mode is enabled in the trace controls.

IMPLICATION: This errata does not affect the normal function of the breakpoint registers.

WORKAROUND: Disable the breakpoints using the Set Breakpoint Register IAC to set bit 1 of both registers to 1. Alternatively, if breakpoints are not being used, do not set the breakpoint trace mode bit in the trace controls.

STATUS: Refer to Summary Table of Changes to determine the affected stepping(s).

SPECIFICATION CHANGES

None for this revision of this specification update.

SPECIFICATION CLARIFICATIONS

None for this revision of this specification update.

DOCUMENTATION CHANGES

None for this revision of the specification update.