



80C186EC/80C188EC AND 80L186EC/80L188EC EMBEDDED MICROPROCESSORS SPECIFICATION UPDATE

Release Date: July, 1996

Order Number 272898-001

The 80C186EC/80C188EC and 80L186EC/80L188EC Embedded Microprocessor may contain design defects or errors known as errata. Characterized errata that may cause the 80C186EC/80C188EC and 80L186EC/80L188EC Embedded Microprocessor's behavior to deviate from published specifications are documented in this specification update.



Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

The 80C186EC/80C188EC and 80L186EC/80L188EC Embedded Microprocessor may contain design defects or errors known as errata. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

* Third-party brands and names are the property of their respective owners.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation
P.O. Box 7641
Mt. Prospect, IL 60056-7641

or call in North America 1-800-879-4683, Europe 44-0-1793-431-155, France 44-0-1793-421-777,
Germany 44-0-1793-421-333 other Countries 708-296-9333

Copyright © 1996, Intel Corporation

CONTENTS

REVISION HISTORY	1
PREFACE	2
SUMMARY TABLE OF CHANGES.....	4
IDENTIFICATION INFORMATION	6
ERRATA	7
SPECIFICATION CHANGES	11
SPECIFICATION CLARIFICATIONS	11
DOCUMENTATION CHANGES	12

REVISION HISTORY

Date of Revision	Version	Description
07/01/96	001	This is the new Specification Update document. It contains all identified errata published prior to this date.



PREFACE

As of July, 1996, Intel's Semiconductor Products Group has consolidated available historical device and documentation errata into this new document type called the Specification Update. We have endeavored to include all documented errata in the consolidation process, however, we make no representations or warranties concerning the completeness of the Specification Update.

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This is the first release of the 80C186EC/80C186EC and 80L186EC/80L188EC Microprocessor Specification Update. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain additional information that was not previously published.

Affected Documents/Related Documents

Title	Order
<i>80C186 Datasheet Errata</i>	272027-001
<i>80C188 Datasheet Errata</i>	272076-001
<i>80C186EC/80C188EC Microprocessor User's Manual</i>	272047-003

Nomenclature

Errata are design defects or errors. These may cause the published (component, board, system) behavior to deviate from published specifications. Hardware and software designed to be used with any component, board, and system must consider all errata documented.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in any new release of the specification.

NOTE:

Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

SUMMARY TABLE OF CHANGES

The following table indicates the errata, specification changes, specification clarifications, or documentation changes which apply the 80C186EC/80C186EC and 80L186EC/80L188EC Embedded Microprocessor. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Steps

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page):	Page location of item in this document.
---------	---

Status

Doc:	Document change or update will be implemented.
Fix:	This erratum is intended to be fixed in a future step of the component.
Fixed:	This erratum has been previously fixed.
NoFix:	There are no plans to fix this erratum.
Eval:	Plans to fix this erratum are under evaluation.

Row

|

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Errata

No.	Steppings			Page	Status	ERRATA
	A	B	AB BB CB			
80C186EC/ 80C188EC						
9600001	X	X	X	7	NoFix	NMI Entering Powerdown Mode on the 80C18x EA/EB/EC
9600002	X			9	Fixed	Early Exit From Reset
9600003	X			10	Fixed	Clock Divider At Reset
9600004	X	X	X	10	NoFix	Watchdog Timer Cannot be Reloaded or Disabled When the Peripheral Control Block (PCB) Is Located in Memory Space

Specification Changes

No.	Steppings			Page	Status	SPECIFICATION CHANGES
	#	#	#			
						None for this revision of this specification update.

Specification Clarifications

No.	Steppings			Page	Status	SPECIFICATION CLARIFICATIONS
	#	#	#			
						None for this revision of this specification update.

Documentation Changes

No.	Document Revision	Page	Status	DOCUMENTATION CHANGES
001	003	12		<i>80C186/80C188 Microprocessor User's Manual Errata</i>
002	003	13		<i>80C186/80C188 Microprocessor User's Manual Errata - Reload Sequence</i>
003	003	14		<i>80C186/80C188 Microprocessor User's Manual Errata - Disabling The Watchdog Timer</i>

IDENTIFICATION INFORMATION

Markings

A-Step sample devices can be identified in two ways:

1. The product is marked with a five character QDF number just below the product identifier. The table below can help you quickly identify which product you have:

Product	QDF Numbers (all packages)
80C186EC	Q8566, Q8568
80C188EC	Q8567, Q8569

2. There is a STEPID register which may be examined through software. For A-step devices, the register contains a value of 01H.

ERRATA**9600001. NMI Entering Powerdown Mode on the 80C18xEA/EB/EC**

PROBLEM: If an NMI can be received during execution of the HLT instruction when entering Powerdown mode, certain considerations must be made.

IMPLICATION: If an NMI occurs during execution of the HLT instruction when entering Powerdown mode, the processor may enter Powerdown or may not service the NMI. To avoid this, the NMI pulse width must be extended to allow recognition.

WORKAROUND:

NMI Functionality - NMI is the highest priority interrupt. It cannot be masked by software. To be recognized, NMI must be active for a minimum of one CLKOUT period and meet required setup and hold times (for recognition at a specific clock edge). If these requirements are met, NMI servicing begins at the next valid instruction boundary.

Powerdown Mode Functionality - Powerdown mode on the 186 processors causes the clock input to the CPU and peripherals to be disabled. To enter Powerdown mode, two things must happen. First, the PWRDN bit in the PWRCON Register must be set.

Second, the HLT instruction must be executed. During the HLT instruction, the clock signal to the CPU and integrated peripherals stop (at a logic low level) at the end of the T2 bus state. The CLKOUT signal stops (at a logic high level) at the end of the T3 bus state. To exit Powerdown, an NMI or processor reset must occur.

NMI During HLT Execution - If an NMI occurs before the HLT instruction executes, everything functions properly. The NMI is recognized at the instruction boundary preceding the HLT instruction, the NMI is serviced and the processor then enters powerdown mode.

The problem occurs when an NMI occurs during execution of the HLT instruction. NMI is only serviced at valid instruction boundaries. The HLT instruction, when entering Powerdown, does not really have a boundary, it extends until Powerdown is exited. If NMI occurs between the beginning the T1 bus state and the end of the T2 state, but does not extend into T3, it will not be recognized, and the processor will enter Powerdown mode. The processor does not recognize the NMI request during the HLT instruction until the internal clock has stopped (at the end of T2).

For the NMI to be recognized during the execution of the HLT instruction, the pulse must extend into T3. At this point, the processor has entered Powerdown and synchronized the NMI pulse. The NMI will be processed, but the processor will never enter Powerdown. Essentially, because NMI is active, the processor exits Powerdown as soon as it enters.

In a typical system design using Powerdown mode, NMI can only occur after Powerdown is entered and the clock is stopped. The simplest solution to the problem is to not assert NMI unless the processor has entered Powerdown Mode.

If the system requires periodic NMI pulses, then the NMI pulse width must be long enough to ensure that it will extend into the T3 state of the HLT instruction. A NMI pulse width of three CLKOUT periods guarantees this.

The figures below show NMI occurring at different times during execution of the HLT instruction. Two cases are shown. Figure 1 shows cases where NMI is not recognized. Figure 2 shows cases where NMI is recognized. Both cases assume setup and hold time requirements are met for the NMI input.




Figure 1. NMI Ignored During HLT Entering Powerdown




Figure 2. NMI Recognized During HLT Entering Powerdown

STATUS: There are no plans to correct this errata. Refer to Summary Table of Changes to determine the affected stepping(s).

9600002. Early Exit From Reset

PROBLEM: At high Vcc voltages and/or low operating temperatures, the 80C186EC/80C188EC will exit reset one CLKOUT cycle too early due to an internal race condition. The device resets correctly and executes code normally (just one clock too early). The problem is aggravated by conditions that tend to cause higher speed internal operation (i.e., high Vcc and low temperatures). The voltage and temperature points at which the anomaly occurs vary from device to device.

IMPLICATION: In most operations this errata causes no impact.

WORKAROUND: None

STATUS: Fixed in B step. Refer to Summary Table of Changes to determine the affected stepping(s).

9600003. *Clock Divider At Reset*

PROBLEM: The clock division circuitry that is used in Powersave Mode may not be reset immediately. The correct design would have reset the Powersave divider immediately upon reset. Instead, the divider is not reset until the first low phase of CLKOUT following a reset.

IMPLICATION: Because the divider is not reset, it is possible that the device could be operating in a divide-by mode. This could have the effect of extending the period of CLKOUT by as much as 64 times the undivided rate for the first cycle out of reset. A minimum of 128 CLKIN pulses are required after RESIN# is asserted to ensure that the Powersave divider is properly cleared after a reset. The 128 CLKIN pulses ensure that at least one full CLKOUT cycle occur for the worst case of divide-by-64 mode.

WORKAROUND: The problem can occur both at cold and warm reset. For a cold reset the fix involves insuring that RESIN# is held low at least 128 CLKIN pulses. Note that the datasheet and handbooks both specify RESIN time with respect to CLKOUT. If these specifications are followed no problems will occur (since it only takes one full CLKOUT after RESIN# is asserted to reset the divider). For a warm reset (including Watchdog Timer reset), if the 4 CLKOUT period minimum is followed no problems will occur if Powersave mode is not being used. If Powersave Mode is active when a warm reset occurs, then the first CLKOUT during reset will be at the divided rate. The subsequent 3 (or more) CLKOUTs will be at full speed.

STATUS: Fixed in B step. Refer to Summary Table of Changes to determine the affected stepping(s).

9600004. *Watchdog Timer Cannot Be Reloaded or Disabled When the Peripheral Control Block (PCB) Is Located in Memory Space***PROBLEM:**

RELOADING THE WATCHDOG TIMER - The Watchdog Timer counter is reloaded by a locked sequence of two separate byte write operations to the Watchdog Timer Clear register (WDTCLR). The first byte of data is 0AAH, and the second byte is 55H. A special LOCKed instruction is required to accomplish this.

The use of the LOCK REP MOVS instruction not only increments/decrements the source address, but also the destination address (WDTCLR). Therefore, the first byte would be written correctly to the WDTCLR register, while the second byte would be written to WDTCLR+1 in memory. This causes the Watchdog Timer not to reload and the WDT to expire.

DISABLING THE WATCHDOG TIMER - A similar two byte write sequence is used to disable the Watchdog Timer. The first byte of data is 55H, and the second byte is 0AAH. This data is written to the Watchdog Timer Disable register (WDTDIS).

Again, it is not possible to disable the Watchdog Timer when the PCB is in memory space because there is no LOCKed string instruction that can be used to write two consecutive bytes to a single memory address (i.e., the MOVS instruction adjusts both the source and destination operands).

IMPLICATION: It is not possible to reload or disable the WDT when the PCB is in memory space because there is no instruction that supports a locked byte string sequence in which the destination address (WDTCLR) stays fixed while the source increments/decrements.

WORKAROUND: Reloading and disabling operations of the Watchdog Timer must be performed with the PCB located in I/O space. If the PCB is to be located in memory space, it must be temporarily moved back into I/O space for reloading or disabling.

NOTE: All serial and "DMA to Internal Peripheral" operations must be temporarily disabled prior to switching the PCB to I/O space. Once the PCB is mapped back to memory space, the serial and "DMA to Internal Peripheral" operations can be re-enabled.

STATUS: There are no plans to correct this errata. Refer to Summary Table of Changes to determine the affected stepping(s).

SPECIFICATION CHANGES

None for this revision of this specification update.

SPECIFICATION CLARIFICATIONS

None for this revision of this specification update.



DOCUMENTATION CHANGES

001. 80C186/C188EC Embedded Microprocessor User's Manual Errata

ISSUE: Please make the following corrections to the *80C186EC/80C188EC Microprocessor User's Manual* and keep this errata sheet with your manual for future reference. These changes will be included in a future revision of this manual.

Page	Change
5-1, section 5.1	Change paragraph to read: "The clock generation circuit (Figure 5-1) includes a crystal oscillator, a divide-by-two counter, power-down, power-save, idle, and reset circuitry. See "Power Management" on page 5-10 for a discussion of power management options."
8-10, 8.3.2.3 Spurious Interrupts Chapter	Change first sentence to read, "For both level- and edge-sensitive interrupts, a high value must be maintained on the IR line until after the falling edge of the first INTA# pulse (see Figure 8-5)."
8-25, Figure 8-13. ICW2 Register	For Bit Mnemonic T7:3, change Function description "For example, write 20H to these bits to specify a Type 8 interrupt" to "For example, write 20H to these bits to specify a Type 32 interrupt"
9-5, Figure 9-3.	The stem below the Conditional statement (upper left of diagram) "Counter = Compare 'A' ?" should be a "YES" and the stem to the right should be a "NO."

002. 80C186/C188EC Embedded Microprocessor User's Manual Errata - Reload Sequence

ISSUE: Please make this correction to the *80C186EC/80C188EC User's Manual*, Example 12-1. The following example code is used to reload the watchdog timer down counter.

```
wdt_data segment

wdt_rel      db      0AAH, 055H          ;WDT Reload Constants

wdt_data ends

wdt_reload  segment
            assume cs: wdt_reload, ds: wdt_data

            mov     ax, seg wdt_rel
            mov     ds, ax
            mov     si, offset wdt_rel   ;DS:SI points to the Reload Constants

            cld                                ;Clear direction flag (autoincrement)
            mov     cx, 2                    ;2 byte string operation

            mov     dx, 0FF28h             ;I/O address of WDTCLR

lock_rep    outs   dx, byte ptr ds: [si] ;LOCKed WDT reload sequence

wdt_reload  ends
```

**003. 80C186/C188EC Embedded Microprocessor User's Manual Errata -
Disabling The Watchdog Timer (Peripheral Control Block In I/O Space)**

ISSUE: Please make this correction to the *80C186EC/80C188EC User's Manual*, Example 12-3. The following example code is used to disable the Watchdog Timer down counter.

If the WDT is to be disabled, it must be done prior to the first expiration and prior to it being reloaded by either software or hardware reload (timeout).

```

wdt_data segment

wdt_dis      db      55H, 0AAH          ;WDT Disable Constants

wdt_data ends

wdt_disable  segment
            assume cs: wdt_disable, ds: wdt_data

            mov     ax, seg wdt_dis
            mov     ds, ax
            mov     si, offset wdt_dis  ;DS:SI points to the Disable Constants

            cld                                ;Clear direction flag (autoincrement)
            mov     cx, 2                    ;2 byte string operation

            mov     dx, 0FF2Ah            ;I/O address of WDTDIS

lock rep     outs   dx, byte ptr ds: [si] ;LOCKed WDT disable sequence

wdt_disable  ends

```